OMRON

™ ZG2-WDS3V/WDS3VT

ZG2-WDC□□用 2次元形状計測センサ センサヘッド

取扱説明書

この取扱説明書をお読みの上で、保管、設置、プログラミング、動作、保守 または廃棄をお願いします。ご質問またはご意見がありましたら、弊社担当 者までご相談ください。

詳しいご使用の方法に関しましては、コントローラ操作マニュアルをご覧く



オムロン株式会社

© OMRON Corporation 2008-2016 All Rights Reserved.

安全上のご注意

●警告表示の意味



正しい取扱いをしなければ、この危険のた めに、軽傷・中程度の傷害を負ったり、万 -の場合には重症や死亡にいたる恐れ があります。また、同様に重大な物的損害 を受ける恐れがあります。

●図記号の意味



レーザ光線の危険の可能性を注意する通告に用いる。



分解禁止 機器を分解することで感電などの障害が起こる 可能性がある場合の禁止通告に用いる。

●警告表示

⚠警告

ーザが直接、または鏡面の物体に反射して、目に入らな いようにご注意ください。レーザから放射されたレーザ光を 凝視すると目に障害を引き起こす可能性があります。 こに規定した以外の手順による制御及び調整 は、危険なレーザ放射の被ばくをもたらします。



分解しないでください。分解すると、レーザ光がもれ出し、 目や皮膚に障害を引き起こす可能性があります。



レーザー製品を安全に使用していただくために

レーザ機器に関しては、国内・外でレーザ安全対策が規定されてい ます。国内で使用される場合、国内にて組付けられて海外輸出さ れる場合、これらを5つのケースにわけて説明します。

(1)日本

JIS C6802:2014規格で、レーザー製品のクラスに応じて使用者が 行わなければならない安全予防対策が規定されています。形 ZG2-WDS3V/WDS3VTは本規格に定めるクラス2に分類されま す。形ZG2-WDS3V/WDS3VTはセンサ部側面に以下の警告ラ ベルを貼っています。



機器搭載して米国へ輸出する場合、米国のレーザ規格FDA (Food and Drug Administration)の規制を受けます。 形ZG2-WDS3V/WDS3VTは21CFR1040に定めるクラスIIに分 類されます。形ZG2-WDS3V/WDS3VTはCDRH(Center for Device and Radiological Health)に届け出済みです 詳細は別途お問い合わせください。

レーザに関するラベル類

FDAの技術基準に従ったラベルを添付していますので、米国へ輸出の際は、下図参照のうえセンサ本体のラベルを貼り替えてください。 形ZG2-WDS3V/WDS3VTは最終システム装置に組み込まれる ことを意図しています。組み込みに際しては、次の技術基準に基づ

米国連邦法:21CFR 1040.10 and 1040.11



形ZG2-WDS3V/WDS3VTは、GB/T 7247.1-2024規格に定めるClass2に分

This laser product complies wit 21 CFR 1040 10 and 1040 11

中国で使用する際は、付属品の中文ラ ベルに貼替えてください。



(4)カナダ 形ZG2-WDS3V/WDS3VTは、IEC60825-1:2014規格に基づき クラス2に分類されています。

(5)日本、米国、中国、カナダを除く諸外国 国内、米国、中国およびカナダ以外の地域については、警告ラベル をその地域に適した付属品のラベルに貼替えてください 形ZG2-WDS3V/WDS3VTは、IEC 60825-1:2014 / EN 60825-1:2014+A11:2021規格でクラス2に分類されます。 ヨーロッパへの輸出向けのラベルは、欧州規格EN 60825-1:2014+A11:2021 に従っています。

LASER RADIATION OT STARE INTO BEAR XIMUM OUTPUT:1,0mW SE DURATION :5msec VE LENGTH :650nn

■ レーザ光線による障害の防止策

また、労働安全衛生法ではレーザを用いた労働について、その安全予防対策の具体的 内容をクラス1、クラス2以外のレーザ機器を対象に「レーザ光線による障害の防止策に ついて」で定めています。以下にそのクラス別措置基準を示します。

措置内容(項目のみ)			措置内容		レーザ機器のクラス				
					3В	3R	2M	1 N	
レーザ機器管理者の選任			レーザ機器の取扱及びレーザ光線による障害の防止に ついて充分な知識と経験を有する者のうちから選任	0	0	0			
管理区域(標識、立入禁止)			他の区域と区画し標識等で明示、関係者以外立入禁止	0	0				
	レーザ光路	光路の位置	作業者の目の高さを避ける				0	C	
		光路の適切な 設計・遮蔽	可能な限り短く折れ曲がる数を最小にして、歩行路と 交差せず可能な限り遮蔽	0	0	0			
		適切な終端	適切な反射率及び耐熱性も持つ拡散反射体又は吸収体 で終端	0	0	0	0	C	
	キーコントロール		キー等により作動する構造	0	0				
レーザ	緊急停止 スイッチ等	緊急停止スイッチ	レーザ光の放出を直ちに停止できる非常停止スイッチ	0	0				
機器		警報装置	容易に確認できる自動表示灯等の警報装置	0	0	0			
		シャッタ	放出口に不意の放出を避けるシャッタ	0	0				
	インターロックシステム等		管理区域開放、光路遮蔽解除時の時レーザ放出自動停止	0	0				
	放出口の表示		レーザ光放出口に表示	0	0	0			
	操作位置		レーザ光路から出来るだけ離れた位置でレーザ機器の制御	0					
	光学系の調整		光学調整時は必要最小限のパワーで行う	0	0	0	0	(
		保護眼鏡	レーザの種類に応じた適切なレーザ用保護眼鏡の着用	0	0	0			
作業	保護具	保護衣	皮膚の露出の少ない作業衣の着用	0	0			Г	
		難燃性素材の 使用	難燃性素材の衣服着用、溶融して玉状になる化学繊維は 不適	0					
管理等	点検·整備		始業点検、一定期間ごとの点検、調整	0	0	0	0	(
	安全衛生教育		労働者の雇い入れ時、作業内容変更時、レーザ機器変更 時の教育	0	0	0	0	(
	健康管理	前眼部検査	雇い入れ又は配置替え時に視力検査と併せて角膜、水晶 体検査	0	0	0			
		眼底検査	雇い入れ又は配置替え時に視力検査と併せて眼底検査	0					
		管理者氏名	レーザ機器管理者氏名	0	0	0		Γ	
その他	揭示	危険性掲示	見やすい箇所に、レーザ光線の危険性、有害性及び取扱 注意事項	0	0	0	0	(
		設置の表示	レーザ設備の標識	0	0			Γ	
	高電圧の表示		高電圧部分の表示、感電防止措置	0	0	0	0	(
	危険物の	管理区域内	爆発物、引火性物質	0				T	
	持込禁止	レーザ光路付近	爆発物、引火性物質	0	0			t	
	有害ガス、粉じん等		労働安全衛生法所定の措置		0			t	
	レーザ光線による障害の疑いの ある者に対する医師の診察・処置		レーザ光による障害が疑われる者には、速やかに医師によ	0	0	0	0	(

安全装備について

形ZG2はレーザ発光警告灯、レーザオフ入力回路を備え ています。外部回路でインタロック機能を構成することが できます。

取扱いについて

- ・光路に鏡面反射体がある場合は、遮光カバーなどを設置し てお使いください。開放して使用しなければならない場合、 光路が目の高さにならないようにしてください。
- ·安全距離(公称眼障害距離:NOHD)は約1mですが、で きるだけ光路を終端にするようにしてください。

終端材は反射の少ない、つや消し塗装面が最適です。

安全上の要点

次に示す項目は安全を確保するために必ず守ってください。 引火性・爆発性ガスの環境では使用しないでください。

- 操作・保守の安全性を確保するため、高圧機器や動 力機器から離して設置してください。
- 指定された電源電圧で使用してください。
- 取付において、ねじの締め付けは確実に行ってください。 この製品を分解したり、修理、改造しないでください。
- 廃棄するときは、産業廃棄物として処理してください。

使用上の注意

製品が動作不能、誤動作、または性能・機能への悪影響 を防ぐため、以下のことを守ってください。

(1)設置場所について

次のような場所には設置しないでください。

・周囲温度が定格の範囲を超える場所 ・温度変化が急激な場所(結露する場所)

・腐食性ガス、可燃性ガスがある場所

- ・相対湿度が35~85%RHの範囲を超える場所
- ・塵埃、塩分、鉄粉がある場所
- ・振動や衝撃が直接加わる場所
- ・強い外乱光(レーザ光、アーク溶接光など)があたる場所 ・直射日光があたる場所
- ・水・油・化学薬品の飛沫がある場所
- ・強磁界、強電界がある場所

(2)構成品について

コントローラは、必ず専用品をお使いください。

(3)センサについて

- センサ部前面の光学フィルタには、ほこりや油滴などが 付かないような場所に設置してください。万一付いた場 合は、次のように清掃してください。
- ・大きなごみ、ほこりはブロアブラシ (カメラレンズ用)で吹 き飛ばしてください。呼気で吹き飛ばすことは避けてく
- ・小さなごみ、ほこりは柔らかい布 (レンズクリーナなど)に アルコールを少量含ませて、ていねいに拭き取ってく ださい

強く拭くことは避けてください。フィルタにきずが付くと誤 差の原因となります。

(4)環境について

ワークの材質、形状によって、測定できない場合や精度 が出ない場合があります。(反射率の極端に小さな材 質、曲率の小さな対象物、大きく傾斜した対象物など) ヘッドの清掃には、シンナー、ベンジン、アセトン、灯油類 は使用しないでください。

(5)ウォームアップについて


電源投入後約30分間放置してからお使いください。 電源投入直後は回路が安定していませんので、測定 値が徐々にドリフトすることがあります。

(6)外乱光の影響について

- ・センサヘッドの光学フィルタに強い照明があたる設置は
- ・被測定ワークに光沢がある場合、照明光が映り、誤 動作することがあります。その場合、照明を覆うなどして 映り込みを防いでください。

項目 形式		形ZG2-WDS3V/WDS3VT					
光学方式		正反射	拡散反射				
計測中心路	巨離(高さ方向)	22.3mm	10.6mm				
計測範囲	幅方向	3mmTYP					
日1750年6月1	高さ方向	±0.5mm	±0.4mm				
光源		可視半導体レーザ(波長 650nm, 1mWMAX, JIS クラス2,IEC/EN クラス2,FDA クラスII)					
ビーム形状	(*1)	25µm×4mmTYP.(計測中心距離において)					
幅方向分解	幹能	5μm(3mm/631pix)					
高さ方向分	解能(*2)	0.2μm					
高さ方向リ	ニアリティ(*3)	±0.1% F.S.					
LED 表示的	灯(*4)	レーザ発光警告灯です。レーザ発光準備が整っていることを示す「スタンバイ表示灯(STANBY)」と、レーザ発光中であることを示す「レーザ動作表示灯(LD ON)」があります。電源投入後、起動完了までの期間は、両方の表示灯が消灯します。					
計測対象物	TO TO THE PARTY OF	不透明体/透明体表面					
温度特性(*5)	0.08% F.S./°C					
	保護構造	IP67(IEC60529)					
	使用周囲照度	受光面照度 7,000lx以下(白熱ランプ)					
耐環境性	周囲温度	動作時:0~+50℃ 保存時:-15~+60℃(ただし氷結しないこと)					
	周囲湿度	動作時・保存時:各35~85%RH(ただし氷結・結露しないこと)					
	耐振動(耐久)	10~150Hz(片振幅0.35mm) X,Y,Z方向 80mi					
	衝撃(耐久)	150m/s ² 6方向、各	·3回(上下·左右·前後)				
材質		ケース:アルミダイカスト ケーブル外被:耐熱塩化ビニール コネクタ:亜鉛合金および黄銅 前面カバー:ガラス					
コード長		0.5m / 2m (耐屈曲ケーブル)					
最小曲げ半	4径	68mm					
質量	<u> </u>	約300g					
付属品		レーザ関連ラベル(EN:1枚、FDA:3枚、GB:1枚) フェライトコア大(1個)、フェライトコア小(1個)					


- 中心光強度の1/e²(13.5%)で定義。定義域外にも漏れ光があり、ワーク周囲の光の反 射率がワークに比べて高い状況では、影響がでる場合があります。
- 当社標準の鏡面体(正反射モード)あるいは当社標準の拡散反射体(拡散反射モード) を計測中心距離に設置し、全ライン平均高さ測定を行った場合。CCDモードは高精度 モード。平均回数は64回。ただし強い電磁界内では、分解能の性能を満足できないこと があります。ZG2-WDS3VTの最小分解能は 0.25μ mです。
- 当社標準の鏡面体(正反射モード)あるいは当社標準の拡散反射体(拡散反射モード) で全ライン平均高さ測定を行った時の理想直線に対する誤差。CCDモードは高精度モ ード。ワークによってリニアリティは変わることがあります。(図1)
- 点灯動作は表1のとおりです。



(表1) 状態表示灯 起動時 RUN/ADJ/FUNモード I D消灯動作中* LD点灯動作中 スタンバイ表示灯 消灯 点灯 (STANDBY) レーザ表示灯 (LD ON) 消灯 消灯 点灯 * LD OFF入力時を含みます。


センサ部とワークの間をアルミの治具で固定した場合の値です。CCDモードは標準モード。

■ センサ外形



センサの接続について

センサケーブルには、付属品のフェライトコアを必ず取付けて ください。取付位置は、センサ側100mm以内に1個(大)、コン トローラコネクタ側から100mm以内に1個(小)です。 センサ側は1ターンして取付けてください。



注:ケーブルは1ターンして取り付けてください。



当社商品は、一般工業製品向けの汎用品として設計製造されています。従いまして、次に 掲げる用途での使用を意図しておらず、お客様が当社商品をこれらの用途に使用される際 には、当社は当社商品に対して一切保証をいたしません。ただし、次に掲げる用途であって 当社の意図した特別な商品用途の場合や特別の合意がある場合は除きます。 (a) 高い安全性が必要とされる用途(例)原子力制御設備、燃焼設備、航空・宇宙設備、鉄 送地機・胃砂路と機・低砂機・ 医甲機製・20分割、2004年へ急校は「発行 道設備、昇降設備、娯楽設備、医用機器、安全装置、その他生命・身体に危険が及び

(b) 高い信頼性が必要な用途(例:ガス・水道・電気等の供給システム、24時間連続運転

システム、決済システムほか権利・財産を取扱う用途など) (c) 厳しい条件または環境での用途(例:屋外に設置する設備、化学的汚染を被る設備。

電磁的妨害を被る設備、振動・衝撃を受ける設備など) (d) カタログ等に記載のない条件や環境での用途 *(a)から(d)に記載されている他、本カタログ等記載の商品は自動車(二輪車含む。以下同

じ)向けではありません。自動車に搭載する用途には利用しないで下さい。自動車搭載用 商品については当社営業担当者にご相談ください。 上記は適合用途の条件の一部です。当社のベスト、総合カタログ、データシート等最新版

のカタログ、マニュアルに記載の保証・免責事項の内容をよく読んでご使用ください

オムロン株式会社 インダストリアルオートメーションビジネスカンパニー ●製品に関するお問い合わせ先

お客様相談室 **川端0120-919-066** 電話 055-982-5015(通話料がかかります)

ー オムロンFAクイックチャット
www.fa.omron.co.jp/contact/tech/chat/
技術相談員にチャットでお問い合わせいただけます。

■営業時間:9:00~17:00 (土曜日、日曜日、12月31日~翌年1月3日を除く ●FAXやWebページでもお問い合わせいただけます。 FAX 055-982-5051 / www.fa.omron.co.ip

●その他のお問い合わせ 納期・価格・サンブル・仕様書は貴社のお取引先、または貴社 担当オムロン販売員にご相談ください。 オムロン制御機器販売店やオムロン販売拠点は、Webページで

A図 2024年12月

OMRON ZG2-WDS3V/WDS3VT

Sensor Head for Profile Measuring Sensor ZG2-WDC

INSTRUCTION SHEET

Please read and understand this instruction sheet before storing, installing, programming, operating, maintaining, or disposing of the products. Please consult your OMRON representative if you have any questions or comments.

Please refer to the Controller Operating Manual for

detailed instructions on usage

TRACEABILITY INFORMATION:

mporter in EU:
Omron Europe B.V.
Wegalaan 67-69
2132 JD Hoofddorp,

nanufacturer: Omron Corporation, Shiokoji Horikawa, Shimogyo-ku, Kyoto 600-8530 JAPAN

The following notice applies only to products that carry the CE mark

This is a class A product. In residential areas it may cause radio interference, in which case the user may be required to take adequate measures to reduce interference.

© OMRON Corporation 2008-2016 All Rights Reserved.

PRECAUTIONS ON SAFETY

Meaning of Signal Words



Indicates a potentially hazardous situation which, if not avoided, will result in minor or moderate injury, or may result in serious injury or death. Additionally there may be significant property damage.

Meanings of Alert Symbols



Laser beam Cautions to indicate potential laser beam hazard




Do not disassemble Indicates prohibition when there is a risk of minor injury from electrical shock or other source if the product is disassembled.

Alert Statements / Messages d'alerte

⚠ WARNING / AVERTISSEMENT

Looking into the Outgoing light continuously may cause visual impairment. Do not look directly into the Outgoing light. Caution-Use of controls or adjustments or performance of procedures other than those specified herein may result in hazardous radiation



Attention-L'utilisation des commandes ou réglages ou l'exécution des procédures autres que celle spécifiées dans les présentes exigences peuvent étre la cause d'une exposition à un rayonnement

Do not disassemble this product. Doing so may cause exposure to the built-in light source which can damage eyes and skin. Never disassemble it.



SAFETY PRECAUTIONS FOR USING LASER EQUIPMENT PRÉCAUTIONS DE SÉCURITÉ POUR L'UTILISATION D'ÉQUIPEMENTS LASER

Laser safety measures for laser devices are stipulated both in Japan and overseas. Here, five cases are described. (1)Usage in Japan

The JIS C6802:2014 standard stipulates the safety precautions that users must take according to the class of the laser product. The ZG2-WDS3V/WDS3VT is classified into class 2 defined by this standard. The ZG2-WDS3V/WDS3VT has the following warning label on the side of sensors




(2)USA

When a laser device is exported to the USA, it falls under the laser regulations of the FDA(Food and Drug Administration). The ZG2-WDS3V/WDS3VT is classified as a class-II laser by 21CFR1040, and it has already been registered with the CDRH(Center for Devices and Radiological Health). Ask your OMRON representative for details. Technical standards have been provided with the ZG2-WDS3V/WDS3VT. When exporting to the USA, refer to the

following illustration and replace the label with the caution label. It is assumed that the ZG2-WDS3V/WDS3VT will be incorporated a final system device. When incorporating the ZG2-WDS3V/WDS3VT, comply with the following technical standards: US Federal Law 21 CFR 1040.10 and 1040.11.

EXPOSURE Class II Caution Labe

CAUTION





(3)China The ZG2-WDS3V/WDS3VT is classified into Class 2 by the GB/T 7247.1-2024 standard. When using in China, warning labels must be replaced by Chinese ones supplied with the product.



(4)Canada The ZG2-WDS3V/WDS3VT is Classified into Class 2 by the IEC60825-1:2014 standard. Le ZG2-WDS3V/WDS3VT est classé dans la classe 2 selon



la norme IEC 60825-1:2014



(5)For countries other than Japan, U.S., China and Canada When usage in countries other than Japan, U.S., China and Canada, warning labels must be replaced by suitable for the area ones supplied with the ZG2-WDS3V/WDS3VT. When exporting to Europe, labels fall under EU standard EN 60825-1:2014+A11:2021. The ZG2-WDS3V/WDS3VT is classified into Class 2 by the IEC 60825-1:2014 / EN 60825-1:2014+A11:2021 standard.



· Safety Devices

The ZG2 is equipped with laser radiation warning lamp and laser off input circuit. Interlocking unit can be configured in the external circuit.

- Usage
- · Use laser enclosure device to prevent specular object from reflecting laser beam. When used without an enclosure, be sure to avoid a laser path from eve level.
- · Although the safety distance (NOHD) is approximately 1 m; it is advisable, however, to terminate the laser on its path if possible. Non-reflective, flatting material is recommendable for termination.

Outline of IEC 60825-1 Standard

The following are the safety measures to be taken by the user for each type of laser equipment.

Classification Required Items	Class 1	Class 1M	Class 2	Class 2M	Class 3R	Class 3B	Class 4	
Laser safety officer	Not required visible light type				Not required for visible light type. Required for invisible light type.	Required		
Remote interlock	Not required				Connect to room or door circuits.			
Key control	Not required				Remove key when not in use.			
Beam attenuator	Not required				When in use prevents inadvertent exposure.			
Emission indicator device	Not required by the Not required for visible light type. Required for linvisible light type.				Indicates laser is energized.			
Warning signs	Not required				Follow precautions on warning signs.			
Beam path	Not required Note1. Not required Note2. Terminate bear			am at end of useful length.				
Specular reflection	Not required	Note1.	Not required	Note2.	Prevent unir	ntentional reflections.		
Eye protection	· ·	Not required				Required if engineering and administrative procedures not practicable and MPE exceeded.		
Protective clothing	Not required				Sometimes Specific requiremen			
Training	Not required Note1. Note1. Note2. Required for all operator and maintenance personnel							
Note1. Class 1M laser product on condition 1 in table 10 in IEC 60825-1 is required. Class 1M laser product on condition 2 is not required. Note2. Class 2M laser product on condition 1 in table 10 in IEC 60825-1								

ss 2M laser product on condition 1 in table 10 in IEC 60825is required. Class 2M laser product on condition 2 is not required.

PRECAUTION FOR SAFE USE

Please observe the following precautions for safe use of the products

- (1) Do not use the product in environments where it can be exposed to inflammable/explosive gas.
- (2) Do not install the product close to high-voltage devices and power devices in order to secure the safety of operation and maintenance
- (3) Make sure to use the product with the power supply voltage specified.
- (4) Make sure to tighten all installation screws
- (5) Do not disassemble, repair, or modify the product. (6) Dispose of this product as industrial waste

PRECAUTION FOR CORRECT USE

Please observe the following precautions to prevent failure to operate, malfunctions, or undesirable effects on product performance.

- (1) Do not install the product in locations subjected to the following conditions:
 - · Condensation caused by high humidity · Sudden changes in humidity
 - ·Cold conditions that may cause freezing
 - Presence of corrosive or flammable gases Direct vibration or shock
 - ·Build-up of dust or metal chips Spraying byorganic solvents, water, oil or other

 - Strong magnetic or electric field
 - Reflection of intense light(such as other laser beams or electric arc-welding machines) or generation of strong electromagnetic waves
- (2) Component
- Use only products that have been made expressly for the controller.
- (3) Sensor

Install the sensor in a clean environment and keep the optical filter on the front panel of the sensor free from oil and dust. · If affected by oil or dust.clean the filter as follows:

Use a blower brush (normally used to clean camera lenses) to blow large dust particles away from the surface. Do not blow the dust away with

Gently wipe small dirt or dust particles off with a soft cloth (such as a lens cleaning cloth) dampened with a small amount of alcohol Do not wipe too vigorously. Scratches on the filter

may cause errors later. (4) Environment

The sensor cannot detect the following types of objects accurately:Materials with extremely small reflectances, objects with small curvatures, or objects tilted to a large degree.

(5) Warming Up

After turning on the power supply, allow the Controller to stand for at least 30 minutes before use. The circuits are unstable immediately after the power supply is turned on and attempting measurement may result in inconsistent measurement values.


(6)Influence of external light

Do not install a sensor head under the condition that strong light.


·When a target is glossy, the target might reflect another light such as fluorescent from ceiling into the sensor head, which might cause malfunction. In this case, prerent the light from being incident into the sensor head

■Sensor	 Specification 	ons					
Model	-	ZG2-WDS3V/WDS3VT					
Sensor Installation		Mirror reflection	Diffuse reflection				
Reference distance		22.3mm	10.6mm				
(direction o	of height)						
Measure- Direction of width		3mmTYP					
ment range	Direction of height	\pm 0.5mm	±0.4mm				
Light source	e	Visible Semiconductor Laser					
		(Wave length:650nm,1mW max,JIS class2, IEC/EN class 2,FDA classII)					
Beam dime	ensions *1	25μm×4mm typical at the reference distance					
Resolution in the	e direction of width	5μm(3mm/631pix)					
Resolution in the	e direction of hight *2	0.2μm					
Linearity in the o	direction of hight *3	±0.1%FS					
LED indica	tor lamp *4	There are two indicators for the laser status.					
		"STANDBY":The laser is ready to emit light."LD ON":The laser is emitting light.					
		Both indicators are OFF until the sensor is ready to work after power turns ON.					
Detection of	bject	Opague object/Transparent object					
	characteristic *5	0.08%F.S/°C					
Operation	Degree of protection	IP67(IEC60529)					
environment Ambient operating illumination Illumination at light-receiving surface:7,000 lx r		ce:7,000 lx max,incandescent light					
robustness	Ambient temperature	Operating:0 to +50°C					
		Storage: -15 to +60°C(no freezing and condensation)					
	Ambient humidity	Operating and strage:35% to 85%(no condensation)					
	Vibration(durability)	10 to 150Hz (amplitude of one side:0.35mm)X,Y,Z Direction 80min each					
	Impact(durability)	150m/s ² (6direction and 3times for each)					
Materials		Body:Aluminum die-cast					
		Cable sheating:Heart-resistant PVC					
		Connector:Zinc alloy and brass					
		Front Cover:glass					
Cable lengt		0.5m / 2m (Crooked-proof cable)					
	ending radius	68mm					
Weight		Approx.300g					
Accessorie	S	Laser Label (EN:1, FDA:3, GB:1),Ferrite core (Big and Small size : each 1pcs)					

- *1 Defined as 1/e² (13.5%) of the central light intensity. Leakage of light is also present in areas other than those defined. Thus, there are some influences in cases where the reflection factor of the area surrounding the workpiece is higher than that of the workpiece itself.
- *2 When an OMBON-standard workpiece (Mirror reflection object(Mirror reflection mode)or witch our standard diffuse reflection object(diffuse reflection mode))is placed at reference distance, and its average height of all lines is measured. The average of 64 measurements is taken. Note that the resolution performance may not be satisfied in the presence of strong magnetic fields. Minimum resolution of ZG2-WDS3VT is 0.25 µm. The CCD mode is HI-RESO
- *3 The error in relation to the ideal straight line when the average height of all lines on an OMRON-standard workpiece (Mirror reflection object(Mirror reflection mode)or witch our standard diffuse reflection object(diffuse reflection mode)) is measured. The degree of linearity may change depending on the workpiece.(Drawing1) The CCD mode is HI-RESO.
- *4 The lighting operation is Table1



*5 The value obtained at measurement with the space between the sensor and the workpiece fixed with an aluminum jig. The CCD mode is nomal




SENSOR CONNECTIONS

Two ferrite cores must be attached to the sensor cable. Big ferrite core must be attached within 100 mm from the sensor and small ferrite core must be within 100 mm from the controller's connector, respectively.

Please attach the big ferrite core with 1 turn.

56±0.1



Suitability for Use

M: Months of production 1-9 for Jan.-Sep., X for Oct., Y for

YY: Year of manufacture (last 2 digits of A.D.)

Nov., Z for Dec.

Omron Companies shall not be responsible for conformity with any standards codes or regulations which apply to the combination of the Product in the Buyer's application or use of the Product. At Buyer's request, Omron will provide applicable third party certification documents identifying ratings and imitations of use which apply to the Product. This information by itself is not sufficient for a complete determination of the suitability of the Product in combination with the end product, machine, system, or other application or use. Buyer shall be solely responsible for determining appropriateness of the particular Product with respect to Buyer's application, product or system. Buyer shall take application responsibility in all cases.

NEVER USE THE PRODUCT FOR AN APPLICATION INVOLVING SERIOUS RISK TO LIFE OR PROPERTY WITHOUT ENSURING THAT THE SYSTEM AS A WHOLE HAS BEEN DESIGNED TO ADDRESS THE RISKS, AND THAT THE OMRON PRODUCT(S) IS PROPERLY RATED AND INSTALLED FOR THE INTENDED USE WITHIN THE OVERALL EQUIPMENT OR SYSTEM.

